



Republic of the Philippines
Department of Education

DIVISION OF MALAYBALAY CITY

DM-2019-03-098
DEPED MALAYBALAY CITY DIVISION
RELEASED
MAR DATE: 9 2019 TIME: 9:27
BY: [Signature]

DIVISION MEMORANDUM

No. 098, s. 2019

**TO: Assistant Schools Division Superintendent
Chief Education Supervisors, SGOD and CID
Public Elementary and Secondary School Heads
This Division**

FROM: REBONFAMIL R. BAGUIO
Schools Division Superintendent

DATE: March 15, 2019

SUBJECT: COMPLIANCE TO RA 9514 (REVISED FIRE CODE OF THE PHILIPPINES OF 2008)

1. In partnership with the Bureau of Fire Protection – Malaybalay City Fire Station, fire safety inspections were conducted to schools as pursuant to DepED Order No. 28, s. 2016 re: Strengthening Fire Safety Awareness Program. The result of the activity was the Inventory of Public Schools not Compliant to RA 9514.
2. Relative thereto, **School Heads** mentioned in the inventory shall immediately act on how to address the deficiencies.
3. Should there be queries, contact **Jimdandy S. Lucine**, Project Development Officer II, through **0917 115 6864**.

Encls:

Enclosure A – BFP – MCFS Letter

Enclosure B – Inventory of Public Schools not Compliant to RA 9514

Copy Furnished: Records Unit | DRRM
TO BE POSTED IN THE WEBSITE

Enclosure A



Republic of the Philippines
Department of the Interior and Local Government
BUREAU OF FIRE PROTECTION
Regional Office 10
Bukidnon Provincial Office
Malaybalay City Fire Station
Melendez St., Malaybalay City
Tel. No. 088-813-5449
Email: malaybalaycfs_bfp10@yahoo.com



March 8, 2019

REBONFAMIL R. BAGUIO, Ph.D.
Schools Division Superintendent
DepEd – Division of Malaybalay City

2019-03-06/7
DEPED MALAYBALAY CITY DIVISION
RECEIVED
DATE: MARCH 11, 2019
BY: [Signature]

Sir:

Greetings!

In line with the aim of the Bureau of Fire Protection to keep a fire safe community part of our mandate is to conduct Fire Safety Inspection to various buildings and establishments to ensure their compliance to RA 9514 otherwise known as the Fire Code of the Philippines. It is crucial that we identify unsafe practices and correct them to prevent fire and other mishaps from occurring. Thus we bring to your attention that numerous public schools within Malaybalay are not compliant to the provisions of the Fire Code. Attached with this is a list of all non-compliant schools within the Division of Malaybalay for your perusal.

The undersigned would like to coordinate with your office concerning the compliance of the mentioned schools. As an education stakeholder, we sincerely hope for your immediate action to resolve the matter on hand. You may contact or visit me anytime to discuss the further provisions of the law.

Thank you very much for your support in this endeavor to attain a fire-free and fire-safe community.

Very truly yours,


LLOYD M. VILLAROYA
SINSP BFP
City Fire Marshal



Republic of the Philippines
Department of the Interior and Local Government

BUREAU OF FIRE PROTECTION

Regional Office 10
Bukidnon Provincial Office
Municipal Fire Station
Melendez St., Malaybalay City
Tel. No. 088-813-5449
Email: malaybalaycfs_bfp10@yahoo.com



INVENTORY OF PUBLIC SCHOOLS NOT COMPLIANT TO RA 9514

NO	NAME	VIOLATIONS NOTED/ FOR COMPLIANCE
1	MALAYBALAY CITY CENTRAL SCHOOL	ELECTRICAL WIRING ARE STANDARD, ALL CLASSROOMS PREPARED FOR SYNCHRONIZED BRGY AND SANGGUNIANG KABATAAN ELECTION
2	SUMPONG CENTRAL SCHOOL	ELECTRICAL WIRING ARE STANDARD, ALL CLASSROOMS PREPARED FOR SYNCHRONIZED BRGY AND SANGGUNIANG KABATAAN ELECTION
3	CASISANG STAND ALONE SENIOR HIGH SCHOOL BUILDING 1 & 2	PROVIDE ATLEAST 1 UNIT FFA IN EACH CLASSROOM
4	CASISANG CENTRAL SCHOOL	PROVIDE CENTRALIZED FIRE ALARM SYSTEM, PROVIDE 1 UNIT FFA IN EVERY ROOM, PROVIDE EMERGENCY ACCESS ROOM
5	AIRPORT VILLAGE ELEMENTARY SCHOOL	PROVIDE CENTRALIZED FIRE ALARM SYSTEM, PROVIDE 1 UNIT FFA IN EVERY ROOM
6	CASISANG NATIONAL HIGH SCHOOL	PROVIDE ATLEAST 2 SWING-OUT DOOR IN EVERY ROOM, PROVIDE CENTRALIZED FIRE ALARM SYSTEM, EXISTING 2 UNITS FFA SUBJECT FOR SERVICING AND MAINTENANCE, PROVIDE 1 UNIT FFA IN EVERY ROOM
7	KALASUNGAY NATIONAL HIGH SCHOOL	INADEQUATE FFA
8	BNHS GYMNASIUM	NO EMERGENCY LIGHTS, NO FFA, INADEQUATE EMERGENCY ALARM SYSTEM
9	BNHS LGU MAIN BUILDING	SWING IN DOOR, INADEQUATE FFA, NO LUMINOUS EXIT SIGNAGES, DEFECTIVE FIRE ALARM
10	BNHS GRADE 8 & 9	DEFECTIVE ALARM SYSTEM, PROVIDE ATLEAST 2 DOORS IN EVERY CLASSROOM, PROVIDE 1 UNIT FFA PER CLASSROOM
11	BNHS AGRICULTURAL ARTS BUILDING	NO ACCESS ROAD FOR EMERGENCY AND RESCUE VEHICLES, DEFECTIVE ALARM SYSTEM, NO FFA
12	BNHS DOST BUILDING	INADEQUATE EMERGENCY ALARM SYSTEM, INADEQUATE FFA
13	BNHS DEPED NEW BUILDING #4	NO SMOKE DETECTOR
14	BNHS DEPED NEW BUILDING #1	PROVIDE 1 UNIT SMOKE DETECTOR IN EVERY CLASSROOM
15	BNHS DEPED NEW BUILDING #3	PROVIDE 1 UNIT SMOKE DETECTOR IN EVERY CLASSROOM
16	BNHS DEPED BUILDING #2	PROVIDE 1 UNIT SMOKE DETECTOR IN EVERY CLASSROOM
17	BNHS ADMIN BUILDING	NO SMOKE DETECTOR, INADEQUATE FFA
18	BNHS AUTOMATIVE, ELECTRICITY, ELECTRONIC, HORTICULTURE AND COOKERY ROOMS	NO FIRE ALARM, NO FFA
19	BNHS SCIENCE & TECHNOLOGY BLDG	NO ACCESS ROAD FOR EMERGENCY AND RESCUE VEHICLES, DEFECTIVE ALARM SYSTEM, NOEXIT SIGNAGE, SWING IN DOOR/ AGAINST THE DIRECTION OF EXIT, INADEQUATE FFA
20	BNHS MAIN CAMPUS / SPA BUILDING	PROVIDE FIRE ALARM, INSTALL FFA ATLEAST 2 UNITS PER FLOOR
21	BNHS MAIN CAMPUS / 6-8, CARPENTRY, STEEL TECH, MARCOS BLDG, PTA BLDG	NO SMOKE DETECTOR, NO FIRE ALARM, INADEQUATE FFA, SOME DOORS ARE SWING IN/ AGAINST THE DIRECTION OF EXIT
22	BANGCUD CENTRAL SCHOOL	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FIRE ALARM BELL, PROVIDE FFA IN EVERY ROOM
23	APD MACOTE NATIONAL HIGH SCHOOL	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FIRE ALARM BELL, PROVIDE FFA IN EVERY ROOM
24	MANAGOK NATIONAL HIGH SCHOOL - MIGLAMIN ANNEX	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FIRE ALARM BELL, PROVIDE FFA IN EVERY ROOM, DOORS MUST SWING TO THE DIRECTION OF EXIT
25	MALAPGAP ELEMENTARY SCHOOL	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FIRE ALARM BELL, PROVIDE FFA IN EVERY ROOM
26	DALWANGAN ELEMENTARY SCHOOL	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FIRE ALARM BELL, PROVIDE 22 UNITS FFA
27	LANGASIHAN ELEMENTARY SCHOOL	SECURE LATEST ELECTRICAL INSPECTION CERTIFICATE, PROVIDE FFA IN EVERY ROOM
28	ZAMBOANGUITA ELEMENTARY SCHOOL	NO FIRE ALARM, INADEQUATE FFA
29	ST. PETER NATIONAL HIGH SCHOOL	DOORS FOR CLASSROOM 1,2,11,12 AND COMPUTER LABORATORY SHOULD SWING IN THE DIRECTION OF EXIT TRAVEL, REQUIRED TO UNDERGO FIRE DRILL
30	ST. PETER ELEMENTARY SCHOOL	DOORS SWING IN THE DIRECTION OF EXIT TRAVEL, REQUIRED TO UNDERGO FIRE DRILL
31	PIGPAMUHALAN ELEMENTARY SCHOOL	INSTALL ALARM BELL, PROVIDE 3 UNITS FFA, REQUIRED TO UNDERGO FIRE DRILL
32	KIBALABAG ELEMENTARY SCHOOL	PROVIDE ATLEAST 1 UNIT FFA PER CLASSROOM, REQUIRED TO UNDERGO FIRE DRILL

Prepared by:

Verified by:

Noted by:

FO1 Ailyn P Equipelag
FSIS Clerk

FO3 Astrophel C Mulet
Chief Fire Safety and Enforcement Section

SINSE LLOYD M VILLARROYA
City Fire Marshal